







Image Source: 1956 Aerial Photograph.











\* Source: Lockheed Martin SERAS 2016.









LPA-SB-04

LPA-SB-05 \_\_LPA-SB-06

LPA-SB-15

LPA-SB-18

LPA-SB-01

LPA-SB-08

LPA-SB-16

LPA-SB-07

LPA-SB-10

LPA-SB-11

LPA-SB-19

LPA-SB-30

LPA-SB-24

LPA-SB-26

LPA-SB-03

LPA-SB-02 54

LPA-SB-09

LPA-SB-12

LPA-SB-20


LPA-SB-27 LPA-SB-21

LPA-SB-28

LPA-SB-29

LPA-SB-13

LPA-SB-17





Sampling and Analysis Plan for Remedial Investigation for Wilcox Oil Company Superfund Site Bristow, Creek County, Oklahoma



\* Source: Lockheed Martin SERAS 2016.





SC-SW/SD-01

ET-SW/SD-08

C1-SW/SD



Sampling and Analysis Plan for Remedial Investigation for Wilcox Oil Company Superfund Site Bristow, Creek County, Oklahoma

